



This is to certify that the Quality Management System of:

**Unlimited Services**

Carretera Internacional km 129  
Parque Industrial Rocafuerte  
Guaymas SO 85400  
Mexico

Central function listed above. See appendix for additional locations  
applicable to:

**The manufacture of electrical harnesses based to the specifications provided and demand agreed with the customer**

has been assessed and approved by  
National Quality Assurance, U.S.A., against the provisions of:

**ISO 9001:2015**

For and on behalf of NQA, USA

Certificate Number: 15810  
EAC Code: 19  
Certified Since: February 27, 1998  
Valid Until: December 21, 2021  
Reissued: March 14, 2019  
Cycle Issued: December 22, 2018



# Certificate of Registration



global assurance

Appendix to Certificate Number: 15810

**Includes Facilities Located at:**

**Unlimited Services**

Certificate Number 15810  
Carretera Internacional km 129  
Parque Industrial Rocafuerte  
Guaymas SO 85400  
Mexico

The manufacture of electrical harnesses based to the specifications provided and demand agreed with the customer

**US Wire Group S. De R.L. De C.V.**

Certificate Number 15810  
Calle Latitud Oriente No. 19  
Parque Industrial Latitud  
Hermosillo-Sonora 83175  
Mexico

The manufacture of electrical harnesses based to the specifications provided and demand agreed with the customer

**Unlimited Services**

Certificate Number 15810  
Building 2 Carretera Internacional km 129,  
Parque Industrial Rocafuerte  
Guaymas SO 85400  
Mexico

The manufacture of electrical harnesses based to the specifications provided and demand agreed with the customer

Certified Since: February 27, 1998

Valid Until: December 21, 2021

Reissued: March 14, 2019

Cycle Issued: December 22, 2018